Software Release



ConfigTool 8.50 Build 1010

Release

granted:

Ralf Landowski

Date:

16.04.2024

Vario V printer added.

New program option: IP addresses can be resolved by DNS name.

New default baud rate settings: 9600 and 57600 (previously 9600 and 19200)

Micra II: When querying the printer status, the current firmware version is also read out.

Software Release



ConfigTool 8.50 Build 1010

Release

granted:

Ralf Landowski

Date: 16.04.2024

8.40 Build 1020

Micra II Printer: When querying the serial settings and the network setting, an error message was displayed even though the printer was ready.

The print storage was not read correctly.

8.40 Build 1010

Firmware update for Linux printers revised.

New printer types: Compa V, Vita V

Network printers: When changing the network settings to DHCP, the new IP address is

not read out correctly.

WLAN Settings: SSIDs with spaces are not accepted correctly by the WLAN module.

8.30 Build 1030

Micra II: Manual firmware update revised.

Micra II: Code pages added

New printer types added: Vita V, Compa V and Micra II

8.30 Build 1010

Micra II printer support added.

Remote Console: Unable to enter letters.

8.20 Build 1020

Firmware update (APL printer): The firmware update aborts with an error message after the file 'Firmware.prn' has been transferred.

8.10 Build 1020

Add Printer Wizard - No printer types could be selected for local printers (LPT/USB).

8.10 Build 1010

Compa V and Vita V printers added

Logging revised

Compa/Vita V - Firmware version and type are not read out correctly.

Firmware Update - The update throws a Timeout exception if the touch panel in the printer needs to be updated.

8.00 Build 1010

TCPConnectTimeout - New setting added (default: 5s)

Remote Console - Standalone application that can be used with the ConfigTool application.

.NET Framework 4.7.2

All releases from Version 8.x are 64-bit only. All releases before Version 8.x are 32-bit only.